

# Hunter Cap and spindle assembly type WRC (7032944)



**Hunter®**

# TEKNISKA SPECIFIKATIONER

Typ

WRC

## PRODUKTINFORMATION

Sensor is not turning controller back on after a rain event? Remove spindle assembly to check for debris or damage to the disks.

**Genererad den: 27/05/2026**

Bevo Nordic A/S  
Pakhusgården 54  
5000 Odense C  
Danmark  
+45 66 19 25 45  
[info@bevo.dk](mailto:info@bevo.dk)  
<http://www.bevo.com>